

AD-A072 237

BERGER ASSOCIATES INC HARRISBURG PA

F/G 13/2

NATIONAL DAM INSPECTION PROGRAM. MIDDLE CREEK DAM (NDI NUMBER P--ETC(U)


DACW31-79-C-0012

NL


UNCLASSIFIED

| OF |

AD  
A0722-7



END  
DATE  
FILMED  
9-79  
DDC



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A



DA072237

Distribution Unlimited  
Approved for Public Release  
Contract No. DACW31-79-C-0012

OK

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DDC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

11 May 79

6 National Dam Inspection Program.  
Middle Creek Dam (NDI Number PA-00731,  
DER Number 36-259), Susquehanna River  
Basin, Lancaster County, Pennsylvania.  
Phase I Inspection Report.

15 DACW31-79-C-0012

PREFACE

This report has been prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

12 74p.

411003

23

Accession For	1
AMS GAKK	
DDC TAB	
Unannounced	
Justification	
By	
Distribution	
Availability Codes	
Avail and/or	
Special	
23	



PHASE I REPORT  
NATIONAL DAM INSPECTION PROGRAM

BRIEF ASSESSMENT OF GENERAL CONDITIONS  
AND RECOMMENDATIONS

Name of Dam: MIDDLE CREEK DAM, NDI NO. PA-00731  
State & State No: PENNSYLVANIA, 36-259  
County: LANCASTER  
Stream: MIDDLE CREEK  
Date of Inspection: April 17, 1979

Based on the visual inspection, past performance and the available engineering data, the dam and its appurtenant structures appear to be in good condition.

In accordance with the Corps of Engineers' evaluation guidelines, the combination of storage and spillway capacity is capable of passing 60 percent of the Probable Maximum Flood (PMF). The spillway is considered to be inadequate, but not seriously inadequate.

The following recommendations are made for action by the owner:

1. That the small low spot in the embankment, adjacent to the end of the walkway be filled.
2. That a formal surveillance and downstream warning system be developed to be used during periods of high or prolonged precipitation.


SUBMITTED BY:

BERGER ASSOCIATES, INC.  
HARRISBURG, PENNSYLVANIA


DATE: May 29, 1979



APPROVED BY:

  
G. K. WITHERS  
Colonel, Corps of Engineers  
District Engineer

DATE 27 Jun 79



OVERVIEW  
MIDDLE CREEK DAM

## TABLE OF CONTENTS

	<u>Page</u>
<b>SECTION 1 - <u>PROJECT INFORMATION</u></b>	
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
<b>SECTION 2 - <u>ENGINEERING DATA</u></b>	
2.1 DESIGN	5
2.2 CONSTRUCTION	6
2.3 OPERATION	6
2.4 EVALUATION	6
<b>SECTION 3 - <u>VISUAL INSPECTION</u></b>	
3.1 FINDINGS	8
3.2 EVALUATION	9
<b>SECTION 4 - <u>OPERATIONAL PROCEDURES</u></b>	
4.1 PROCEDURES	10
4.2 MAINTENANCE OF DAM	10
4.3 MAINTENANCE OF OPERATING FACILITIES	10
4.4 WARNING SYSTEM	10
4.5 EVALUATION	10
<b>SECTION 5 - <u>HYDROLOGY/HYDRAULICS</u></b>	
5.1 EVALUATION OF FEATURES	11
<b>SECTION 6 - <u>STRUCTURAL STABILITY</u></b>	
6.1 EVALUATION OF STRUCTURAL STABILITY	13
<b>SECTION 7 - <u>ASSESSMENT AND RECOMMENDATIONS</u></b>	
7.1 DAM ASSESSMENT	15
7.2 RECOMMENDATIONS	15
 APPENDIX A - CHECK LIST OF VISUAL INSPECTION REPORT	
APPENDIX B - CHECK LIST OF ENGINEERING DATA	
APPENDIX C - HYDROLOGY AND HYDRAULIC CALCULATIONS	
APPENDIX D - GEOLOGIC REPORT	
APPENDIX E - PHOTOGRAPHS	
APPENDIX F - PLATES	



PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM

MIDDLE CREEK DAM

NDI-ID NO. PA-00731  
DER-ID NO. 36-259

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

A. Authority

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspections of dams throughout the United States.

B. Purpose

The purpose is to determine if the dam constitutes a hazard to human life and property.

1.2 DESCRIPTION OF PROJECT

A. Description of Dam and Appurtenances

Middle Creek Dam is an earthfill, sheetpile and concrete structure with a total length of about 500 feet. The height of the dam is 18 feet above the streambed with the maximum height of embankment being 10 feet above natural ground. The center half of the structure is a 250 foot long spillway and control structure constructed of two parallel lines of sheetpiling retaining a zoned fill and is capped with concrete. The 15 feet wide control structure is accessible from the left abutment by a walkway. The structure contains a minimum flow sluice gate and a 18-inch by 36-inch drawdown sluice gate. The downstream area, below the vertical drop weir, is protected with an 18-inch thick concrete slab.

The spillway is connected with concrete cutoff walls on top of sheetpiles to the earth embankment at the abutments. The top of the dam is 4.0 feet above weir crest.

B. Location:

Clay Township, Lancaster County  
U.S.G.S. Quadrangle, Womelsdorf, PA  
Latitude 40°-15.9', Longitude 76°-14.3'  
(Appendix F, Plates I and II)

- C. Size Classification: Intermediate (18 feet high, 3,030 acre-feet)
- D. Hazard Classification: High (Section 3.1.E)
- E. Ownership: Pennsylvania Game Commission  
P. O. Box 1567  
Harrisburg, PA 17120
- F. Purpose of Dam: Water Fowl Management
- G. Design and Construction History:

The dam and facilities were designed by Gannett, Fleming, Corddry and Carpenter, Inc., Harrisburg, Pennsylvania. The permit application for construction was approved by the Pennsylvania Department of Environmental Resources (PennDER) on January 12, 1971. The contractor was J. Robert Bazley, Inc., Pottsville, Pennsylvania, who started actual construction on April 1, 1971, and substantially completed the work in December, 1971. The grouting of the rock in the abutments was performed by Coal Drilling Company, a subsidiary of B. H. Mott & Sons, Huntington, West Virginia. The construction was supervised by a resident engineer of the design consultant. Bi-weekly construction reports were submitted to PennDER.

#### H. Normal Operating Procedures

The reservoir is used for water fowl management. A large area around the reservoir provides undisturbed resting, loafing, feeding and nesting areas for resident and migratory water fowl species. The shallow reservoir forms a marshy habitat. The pool level is kept at spillway weir elevation year around.

### 1.3 PERTINENT DATA

#### A. Drainage Area (square miles)

From files -	7.4
Computed for this report -	7.8
Use	7.8

#### B. Discharge at Dam Site (cubic feet per second) See Appendix C for hydraulic calculations

Maximum known flood, since construction of dam, June 22, 1972	1,615
--	-------



Outlet works low pool outlet at pool Elev. 535	36
Outlet works at pool level Elev. 542.5 (spillway crest)	73
Low pool spillway (stop logs removed) at pool Elev. 542.5 (spillway crest)	89
Spillway capacity at pool Elev. 546.5 (top of dam)	7,125
C. <u>Elevation</u> (feet above mean sea level)	
Top of dam	546.5
Spillway crest	542.5
Invert (18-inch x 36-inch sluice gate)	531.25
Streambed at centerline of dam	528.0
D. <u>Reservoir</u> (miles)	
Length of normal pool	1.2
Length of maximum pool	1.4
E. <u>Storage</u> (acre-feet)	
Spillway crest (Elev. 542.5)	1,300
Top of dam (Elev. 546.5)	3,030
F. <u>Reservoir Surface</u> (acres)	
Top of dam (Elev. 546.5) from HEC-1	538
Spillway crest (Elev. 542.5)	365
G. <u>Dam</u> (See Appendix F, Plates III through IX)	
Type: Homogeneous impervious earthfill with a rock facing on both slopes.	
Length: Two abutments each about 100 feet long.	
Height: 18 feet above streambed (sheetpile wall). 10 feet above natural ground (embankment).	

Top Width: 20 feet.

Side Slopes: Upstream - 2.8H to 1V.  
Downstream - 2.5H to 1V.

Zoning: Homogeneous with sheetpiling over part of the length.

Impervious Core: None.

Cutoff: Trench on centerline dam to solid rock with a concrete groutcap.

Grout Curtain: On centerline of trench at abutments only.

H. Outlet Facilities

There are two openings in the concrete wall adjacent to the spillway, on the left side, one controlled by a 6-inch by 6-inch sluice gate and the other by a 18-inch by 36-inch sluice gate. Both gates have an invert elevation of 531.25. In addition, there are two openings 4-feet wide by 5.5-feet high for discharging water over a broadcrested weir at elevation 540.0. These openings are controlled by stop logs.

I. Spillway

Type: Uncontrolled ogee weir with sloping upstream face.

Length of weir: 232.5 feet with vertical concrete abutment walls.

Crest elevation: 542.50.

J. Regulating Outlets

See Section 1.3.H.



## SECTION 2 - ENGINEERING DATA

### 2.1 DESIGN

#### A. Hydrology and Hydraulics

The files of the Pennsylvania Department of Environmental Resources (PennDER) did not contain hydraulic design data for this structure, except the area-capacity curves shown on Plate III, Appendix F. The report on the application for construction stated that the spillway was designed for a Q of 6,500 cfs, slightly more than what was required according to Pennsylvania's C-curve.

A hydrologic and hydraulic study was made by Gannett, Fleming, Corddry and Carpenter, the designer, including rating curves and a review of the depth of tailwater (See Section 5.1.A of this report).

#### B. Embankment

The embankment of Middle River Creek Dam extends over about 100 feet of length at each abutment, where the dam ties into the sidehills. Highways were relocated to the sidehill. A cutoff trench was excavated to top of rock and after installing a grout cap, (see Plate V, Appendix F) grout holes were drilled and pressure grouted. This grout curtain extends over the length of the cutoff trench only. Beyond this trench, a sheetpile wall was driven to the top of rock. Where the embankment slopes down to the spillway training wall, the sheetpile was capped with a concrete wall (I-wall section, see Plate V and IX, Appendix F). The slopes of the embankment are 2.8H to 1V upstream and 2.5H to 1V downstream. The impervious material is protected with a layer of stone, one foot thick, placed on a 9-inch thick gravel bed. The top of the embankment is 20-feet wide and has an 8-inch thick gravel surface.

#### C. Appurtenant Structures

Besides a full set of design drawings in the files of PennDER, the owner and designer have a set of as-built drawings. The design files of the appurtenant structures were reviewed in the consultant's office. These structures consist of a 250-foot long cellular structure between the training walls. For typical sections, see Plate VII and VIII, Appendix F. The actual spillway is formed by two parallel sheetpile walls at 18-foot centers driven to rock and tied together with 2-inch round tie rods. A zoned fill was placed between the sheetpile walls and the fill was capped with an 18-inch thick slab over which the water flows. A modified ogee section was installed at the downstream end of the slab, with the crest being 1.5 feet above the slab. About 23 feet

downstream from the weir, a third parallel sheetpile wall was driven to rock and the surface area between this wall and the weir was paved with a 1.5 foot thick concrete slab. This slab is 12 feet below weir crest.

At the left end of the overflow section is the control structure. This structure consists of a low flow sluice gate (6-inch x 6-inch), a drawdown sluice gate (18-inches x 36-inches) and two openings which can be adjusted with stop logs. The operator stands are on a platform, accessible by a walkway on top of the wingwall.

## 2.2 CONSTRUCTION

The construction of these facilities occurred in 1971 under the supervision of a resident engineer employed by the design engineer. Regular progress reports were submitted to PennDER. These reports and the as-built drawings indicate that the facilities were constructed as designed and that no major modifications occurred. Records of grouting indicate that the grout take was small (average of .24 bag per linear foot of hole).

## 2.3 OPERATION

Records of operation, which would indicate exact pool levels during maximum inflows, are not maintained. The drawdown sluice gate is operated at least twice a year and the pool level is maintained as required for water fowl management.

## 2.4 EVALUATION

### A. Availability

Design drawings were available in the files of PennDER. The design consultant (GFCC) made available to the inspection team the as-built drawings (no changes) and the design calculations for the structural stability of the overflow section and sheetpile walls. The owner has also copies available of the as-built drawings and some of the design calculations.

### B. Adequacy

#### 1. Hydrology and Hydraulics

The available engineering data was adequate to review the designer's criteria used for the hydraulic design of these facilities. For a comparative discussion, reference is made to Section 5 of this report.



## 2. Embankment

Due to the limited height and length of the embankment and the type of construction used, the actual design criteria and design calculations were not extensive. Review of the construction data indicate a more than adequate section for this short embankment.

## 3. Appurtenant Structures

The available engineering data, consisting of calculations and construction drawings indicate an adequately designed facility. The structures were designed for full reservoir, for construction and normal pool condition. Details on the drawing indicate a facility designed according to acceptable engineering practice.

### C. Operating Records

Although formal operating records were not available for review, the visual inspection indicates that the structure has withstood, without damage, the flows experienced since construction was completed in 1971.

### D. Post Construction Changes

No changes or additions have been reported since the construction was completed in 1971.

### SECTION 3 - VISUAL INSPECTION

#### 3.1 FINDINGS

##### A. General

The general appearance of Middle Creek Dam is good. This recently (1971) constructed facility is in apparently good condition, although the area of the toe and sidehills downstream of the dam abutments are wet and soft. A field office, with a visitor's center, is located about half a mile upstream of the dam. The inspection team was accompanied for a short time by Mr. C. L. Strouphar, Manager of the facilities. The visual inspection check list is in Appendix A of this report. Photographs taken during the inspection are reproduced in Appendix E.

##### B. Embankment

The embankment consists of only two small sections at the abutments, where the dam abuts into the sidehills. The sidehills were excavated on both sides for new highways, which are located at an elevation higher than the top of the dam. The embankments at the abutments are protected with riprap and the top of the fill is covered with a layer of gravel. The profile and typical section surveyed during the inspection (Plate A-II, Appendix A), indicate that the existing condition is in accordance with the design drawings (Appendix F). Plate A-I, Appendix A, indicates large areas of wet and soft conditions beyond the toe of the dam. The appearance of the water on the sidehills indicate that most of this water originates in the higher surrounding ground. The wet condition can be noticed above and just below normal pool elevations. There were no indications that any water came through the embankment of the dam. There is a small low spot on the crest of the dam adjacent to the footbridge, which needs some fill.

The embankment ties into the spillway sections with concrete walls which were in excellent condition. The wall on the left side carries a small walkway, to the control works, which is incorporated with the spillway section.

##### C. Appurtenant Structures

The appurtenant structures form the largest section of the dam and consist of a 250 foot long concrete and steel sheetpile section, including a 15-foot wide section containing regulating sluice gates and stop logs. The 235 foot long overflow section is in good condition. Water drops 12.0 feet from the weir onto a concrete slab. The flow of water, at the time of inspection, prevented close observation, but all



concrete surfaces appeared in good condition. The top of the weir has two small piers, acting as ice breaking devices. Although the flow of water was small, some tailwater was over the slab, thus, breaking the force of the falling water.

On the left side of the spillway is a small structure containing an 18-inch by 36-inch drawdown sluice gate, a 6-inch by 6-inch low flow gate and two 4-foot wide openings with stop logs.

The drawdown sluice gate was operated satisfactorily during the inspection and was in good condition. The minimum flow gate is always partially open. The stop logs are used to maintain a pool level of 2.5 feet below normal pool if so desired for water fowl management. There are no outlet pipes in this structure.

#### D. Reservoir Area

The immediate reservoir area is partially wooded and partially cultivated. The banks of the reservoir are stable and little siltation occurs. For the purpose of waterfowl management, many small ponds (a total of 70 acres) have been constructed in the area immediately upstream of the reservoir.

#### E. Downstream Channel

The immediate downstream channel has a relatively wide flood plain with normal flow contained in a natural stream. A new two-span bridge is located about 600 feet downstream. It was reported that during the Agnes storm in 1972, the water came to the underside of this bridge.

The valley narrows beyond the bridge and widens again within a mile. Several homes are located close to the stream and it is expected that the hazard to loss of life would increase if the dam fails due to overtopping. The hazard category for this dam is considered to be "High".

### 3.2 EVALUATION

The dam and appurtenant facilities appear to be in good condition. The structural integrity of the dam appears to be good and no signs of deterioration, settlement or movement were discovered during the inspection. A low area adjacent to the footbridge should be filled to crest elevation.

## SECTION 4 - OPERATIONAL PROCEDURES

### 4.1 PROCEDURES

The dam and reservoir are owned by the Pennsylvania Game Commission, who maintain a field office and visitor center close to the dam. Water level in the reservoir is controlled through the year as required for water fowl management.

### 4.2 MAINTENANCE OF DAM

The short length of the earthfill embankments are covered with riprap and gravel and do not need any maintenance at present. The spillway appears to be in good condition and no maintenance work is required.

### 4.3 MAINTENANCE OF OPERATING FACILITIES

The sluice gates are operated several times a year and are greased regularly.

### 4.4 WARNING SYSTEM

Although field personnel drive daily by the facilities, a formal surveillance and downstream warning system has not been established.

### 4.5 EVALUATION

The operational procedures for maintenance of the facilities are good. However, it is recommended that a formal surveillance and downstream warning system be established to be used during periods of heavy or prolonged precipitation.



## SECTION 5 - HYDROLOGY/HYDRAULICS

### 5.1 EVALUATION OF FEATURES

#### A. Design Data

The hydrologic and hydraulic information available from PennDER and from the designer of Middle Creek Dam was quite extensive. An area-capacity curve and spillway rating curve were available. The spillway rating curve indicated a maximum discharge capacity, without overtopping, of 7,844 cfs. This was based on a weir coefficient of 4.09.

The designer had computed a PMF of about 14,400 cfs. The design flood was 6,500 cfs, determined from the PennDER C-curve. No flood routing was available.

The designer had evaluated the effect of the bridge located just downstream of the dam, and determined that the resulting backwater from the design flood would cause the tailwater at the dam to be at about elevation 542.9. This would not affect the discharge capacity.

#### B. Experience Data

There were no records available for past floods, but personnel of the Pennsylvania Game Commission reported that the maximum known flood occurred in June, 1972. At that time the water level rose to an elevation of 18 inches above the spillway crest.

#### C. Visual Observations

On the date of the inspection, no conditions were observed that would indicate that the appurtenant structures of the dam could not operate satisfactorily during a flood event, until the dam is overtopped.

#### D. Overtopping Potential

Middle Creek Dam has a total storage capacity of 3,030 acre-feet and an overall height of 18 feet above streambed, both referenced to the top of the dam. These dimensions indicate a size classification of "Intermediate". The hazard classification is "High" (see Section 3.1.E).

The recommended Spillway Design Flood (SDF) for a dam having the above classifications is the Probable Maximum Flood (PMF). For this dam, the PMF peak inflow is about 14,200 cfs (see Appendix C for HEC-1 inflow computations).

Comparison of the estimated PMF peak inflow of 14,200 cfs with the estimated spillway discharge capacity of 7,125 cfs indicates that a potential for overtopping of the Middle Creek Dam exists.

An estimate of the storage effect of the reservoir and routing of the computed inflow hydrograph through the reservoir shows that this dam does not have the necessary storage available to pass the PMF without overtopping. The spillway-reservoir system can pass a flood event equal to 60% of a PMF (see Sheet 9 of Appendix C).

E. Spillway Adequacy

The intermediate size category and high hazard category, in accordance with the Corps of Engineers criteria and guidelines, indicates that the Spillway Design Flood (SDF) for this dam should be the full Probable Maximum Flood (PMF).

Calculations show that the spillway discharge capacity and reservoir storage capacity combine to handle 60% of the PMF (Refer to Sheet 9 of Appendix C).

Since the spillway discharge and reservoir storage capacity cannot pass the PMF without overtopping, but can pass more than one-half PMF without overtopping, the spillway is considered to be inadequate but not seriously inadequate.

The hydrologic analysis for this investigation was based upon existing conditions of the watershed. The effects of future development were not considered.



## SECTION 6 - STRUCTURAL STABILITY

### 6.1 EVALUATION OF STRUCTURAL STABILITY

#### A. Visual Observation

##### 1. Embankment

There were no visual indications of undue embankment stresses or sloughage and the slopes appear to be stable and adequate. Although the downstream area is wet and soft at several places, it appears that this stems from drainage from the sidehills and roadway cuts rather than through the embankment or its foundation.

##### 2. Appurtenant Structures

The spillway and the operational facilities are all in good condition. The visual observation did not notice any problems in stability or wall movements. All concrete surfaces were in excellent condition. Downstream erosion has not occurred.

#### B. Design or Construction Data

##### 1. Embankment

The available design and construction data indicate that the embankment was designed and constructed in accordance with good engineering practice. The abutments were excavated to rock and the underlying rock strata was grouted. The transition from embankment to the spillway has a sheetpile wall driven to rock and is capped with a concrete wall.

##### 2. Appurtenant Structures

The spillway is constructed on two sheetpile walls driven to rock and tied together with tie rods. The 18 foot wide space between the piles is filled with zoned select material and is topped with a concrete slab. The fill is drained at the downstream side with weep-holes. The design and construction data indicate good engineering and a well detailed structure, adequate in stability for all expected loadings.

#### C. Operating Records

Formal operating records are not maintained. Maximum flow over the spillway occurred during tropical storm Agnes (June, 1972), at which time the depth at the weir was approximately 18 inches. This flow was passed without damage downstream.

D. Post Construction Changes

No reported modifications have been made to the original dam design.

E. Seismic Stability

This dam is located in Seismic Zone 1 and it is considered that the static stability is sufficient to withstand minor earthquake induced dynamic forces. No studies or calculations have been made to confirm this assumption.



## SECTION 7 - ASSESSMENT AND RECOMMENDATIONS

### 7.1 DAM ASSESSMENT

#### A. Safety

The visual inspection, the review of available design data and the operational history indicates that Middle Creek Dam is in good condition and has been designed in accordance with acceptable engineering practice. The maintenance procedures for the embankment and facilities are good.

In accordance with the Corps of Engineers' evaluation guidelines, the combination of storage and spillway capacity is sufficient to pass 60 percent of the Probable Maximum Flood (PMF). The spillway, therefore, is considered to be inadequate, but not seriously inadequate.

#### B. Adequacy of Information

The available data is considered sufficient to make a reasonable assessment of the embankment and facilities.

#### C. Urgency

The recommendations presented as a result of this inspection should be implemented without delay.

#### D. Necessity for Additional Studies

Additional studies are not required at the present time.

### 7.2 RECOMMENDATIONS

#### A. Facilities

The following recommendations are presented for action by the owner:

1. That the low spot in the embankment adjacent to the end of the walkway be filled.

#### B. Operation and Maintenance Procedures

1. That a formal surveillance and downstream warning system be established to be used during periods of high or prolonged precipitation.

**APPENDIX A**

**CHECKLIST OF VISUAL INSPECTION REPORT**

**APPENDIX A**



CHECK LIST

PHASE I - VISUAL INSPECTION REPORT

PA DER # 36-259

NDI NO. PA-00731

NAME OF DAM Middle Creek Dam HAZARD CATEGORY High

TYPE OF DAM Concrete Weir Cap on Steel Sheetpiling - Earthfill abutments

LOCATION Clay TOWNSHIP Lancaster COUNTY, PENNSYLVANIA

INSPECTION DATE 4/17/79 WEATHER Cloudy-Windy TEMPERATURE 40's

INSPECTORS: R. Houseal (Recorder) OWNER'S REPRESENTATIVE(s):

R. Shireman Stroupfar, Manager

A. Bartlett \_\_\_\_\_

H. Jongsma \_\_\_\_\_

NORMAL POOL ELEVATION: 542.5 AT TIME OF INSPECTION:

BREAST ELEVATION: 546.5 POOL ELEVATION: 542.6 (wind)

SPILLWAY ELEVATION: 542.5 TAILWATER ELEVATION: \_\_\_\_\_

MAXIMUM RECORDED POOL ELEVATION: 1972 - Weir + 18"

GENERAL COMMENTS:

Dam presents very good appearance. Water flowing over weir at time of inspection. Dam is almost entirely weir. Short earth embankment sections on both ends of the weir.

VISUAL INSPECTION  
EMBANKMENT

	OBSERVATIONS AND REMARKS
A. SURFACE CRACKS	The embankment portions of this structure are two short sections; one on either side of the weir. These sections are covered with dumped rock on both upstream and downstream slopes. No surface cracks.
B. UNUSUAL MOVEMENT BEYOND TOE	None observed.
C. SLOUGHING OR EROSION OF EMBANKMENT OR ABUTMENT SLOPES	The upstream and downstream slopes are covered with dumped stone - 12-inch size. There is no erosion or sloughing.
D. ALIGNMENT OF CREST: HORIZONTAL: VERTICAL:	Horizontal alignment - good. Good (Refer to Plate A-I, Appendix A).
E. RIPRAP FAILURES	None.
F. JUNCTION EMBANKMENT & ABUTMENT OR SPILLWAY	All junctions appear to be in good condition.
G. SEEPAGE	Seepage exists beyond left embankment slope on the natural hillside. This condition is attributed to natural springs in the hillside and not from the dam. Same condition on right hillside.
H. DRAINS	Low flow control gate. Drawdown control gate.
J. GAGES & RECORDER	None.
K. COVER (GROWTH)	Downstream and upstream - dumped rock. Top - gravel.



VISUAL INSPECTION  
OUTLET WORKS

	OBSERVATIONS AND REMARKS
A. INTAKE STRUCTURE	None.
B. OUTLET STRUCTURE	Outlet from Reservoir - 1. Low flow gate. 2. Blowoff gate. For Management of Reservoir - 1. Two bays of stop logs - 30" vertical distance.
C. OUTLET CHANNEL	Natural stream from spillway apron. All discharges through control gates and stop log openings enter into the spillway apron area.
D. GATES	See B above.
E. EMERGENCY GATE	Blowoff gate: 36-inches x 18-inches.
F. OPERATION & CONTROL	Water fowl management program.
G. BRIDGE (ACCESS)	Concrete walkway on top of retaining walls from left embankment onto gate and stop log control area at left side of spillway.


VISUAL INSPECTION  
SPILLWAY

	OBSERVATIONS AND REMARKS
A. APPROACH CHANNEL	The approach to the spillway is directly from the reservoir - no channel.
B. WEIR: Crest Condition Cracks Deterioration Foundation Abutments	Good. None visible - water flowing over weir. Nil. Could not observe. Good.
C. DISCHARGE CHANNEL: Lining Cracks Stilling Basin	Paved apron below spillway. Concrete - good condition. None. None.
D. BRIDGE & PIERS	None across spillway. Special concrete projections (2) on crest of weir. Reported as ice breaking devices. Refer to drawings for dimensions.
E. GATES & OPERATION EQUIPMENT	Gates are an integral part of the spillway, including low flow control and blowoff control. Blowoff gate was operated for this inspection. Low flow gate is always open.
F. CONTROL & HISTORY	Maximum flow over spillway - 18-Inch June, 1972. Control is in accordance with established water fowl management program.

VISUAL INSPECTION

	OBSERVATIONS AND REMARKS
<u>INSTRUMENTATION</u>	
Monumentation	Benchmarks on walls.
Observation Wells	None.
Weirs	One used some time ago to verify low flow volume. Weir removed.
Piezometers	None.
Staff Gauge	None.
Other	None.
<u>RESERVOIR</u>	
Slopes	Slopes flat and stable.
Sedimentation	None reported.
Watershed Description	Partial woodland, partial cultivated. Many small breeding ponds for water fowl.
<u>DOWNSTREAM CHANNEL</u>	
Condition	Natural stream - first mile narrow valley.
Slopes	Wooded with several homes within 1.5 mile.
Approximate Population	40
No. Homes	15






MIDDLE CREEK DAM  
PA-731

INSPECTION SURVEY

4-17-79

PLATE A-I



**APPENDIX B**  
**CHECKLIST OF ENGINEERING DATA**

**APPENDIX B**



CHECK LIST  
ENGINEERING DATA

PA DER # 36-259

NDI NO. PA-00 731

NAME OF DAM Middle Creek Dam

ITEM	REMARKS
AS-BUILT DRAWINGS	Available at the offices of Gannett, Fleming, Corrdry & Carpenter, Inc. (Designer) and the Pennsylvania Game Commission (Owner).
REGIONAL VICINITY MAP	U.S.G.S. Quadrangle, Womelsdorf, PA See Plate II, Appendix F
CONSTRUCTION HISTORY	Bi-weekly reports by consultants in file of PennDER.
GENERAL PLAN OF DAM	Appendix F, Plate V.
TYPICAL SECTIONS OF DAM	Appendix F, Plates V through IX.
OUTLETS: PLAN DETAILS CONSTRAINTS DISCHARGE RATINGS	See Appendix F. Plate V Plate V through IX. In designer's file.

ENGINEERING DATA

ITEM	REMARKS
RAINFALL & RESERVOIR RECORDS	None.
DESIGN REPORTS	Designer's File.
GEOLOGY REPORTS	Designer's File.
DESIGN COMPUTATIONS: HYDROLOGY & HYDRAULICS DAM STABILITY SEEPAGE STUDIES	Designer's File. None. None.
MATERIALS INVESTIGATIONS: BORING RECORDS LABORATORY FIELD	Designer's File. Designer's File. Designer's File.
POST CONSTRUCTION SURVEYS OF DAM	None.
BORROW SOURCES	Not identified.



ENGINEERING DATA

ITEM	REMARKS
MONITORING SYSTEMS	None.
MODIFICATIONS	None.
HIGH POOL RECORDS	No official records. Estimated at 1.5 feet during Agnes (June, 1972).
POST CONSTRUCTION ENGINEERING STUDIES & REPORTS	None.
PRIOR ACCIDENTS OR FAILURE OF DAM  Description:  Reports:	None.
MAINTENANCE & OPERATION RECORDS	None.
SPILLWAY PLAN, SECTIONS AND DETAILS	See Appendix F, Plates III through IX.

ENGINEERING DATA

ITEM	REMARKS
OPERATING EQUIPMENT, PLANS & DETAILS	Appendix F, Plates III through IX.
CONSTRUCTION RECORDS	PennDER files. Bi-weekly reports.
PREVIOUS INSPECTION REPORTS & DEFICIENCIES	None reported.
MISCELLANEOUS	Not all construction drawings have been reproduced in Section F. Additional drawings available at PennDER, the owner's office and the designer's office.

CHECK LIST  
HYDROLOGIC AND HYDRAULIC  
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: Partial woodland, partial cultivated.

## ELEVATION:

TOP NORMAL POOL & STORAGE CAPACITY: Elev. 542.5 <sup>1750</sup> Acre-FeetTOP FLOOD CONTROL POOL & STORAGE CAPACITY: Elev. 546.5 <sup>3300</sup> Acre-FeetMAXIMUM DESIGN POOL: Elev. 546.5TOP DAM: Elev. 546.5

## SPILLWAY:

a. Elevation 542.5b. Type Modified Ogeec. Width 232.5d. Length 18e. Location Spillover Center of Damf. Number and Type of Gates None.

## OUTLET WORKS:

a. Type Stop logs and sluice gates.b. Location Left abutmentc. Entrance inverts 531.25d. Exit inverts 531.25e. Emergency drawdown facilities 18-inch x 36-inch sluice gate

## HYDROMETEOROLOGICAL GAGES:

a. Type Noneb. Location c. Records MAXIMUM NON-DAMAGING DISCHARGE:



**APPENDIX C**  
**HYDROLOGY AND HYDRAULIC CALCULATIONS**

**APPENDIX C**

SUMMARY DESCRIPTION  
OF  
FLOOD HYDROGRAPH PACKAGE (HEC-1)  
DAM SAFETY VERSION

The hydrologic and hydraulic evaluation for this inspection report has employed computer techniques using the Corps of Engineers computer program identified as the Flood Hydrograph Package (HEC-1) Dam Safety Version.

The program has been designed to enable the user to perform two basic types of hydrologic analyses: (1) the evaluation of the overtopping potential of the dam, and (2) the capability to estimate the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. A brief summary of the computation procedures typically used in the dam overtopping analysis is shown below.

- Development of an inflow hydrograph to the reservoir.
- Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- Routing of the outflow hydrograph(s) of the reservoir to desired downstream locations. The results provide the peak discharge, time of the peak discharge and maximum stage of each routed hydrograph at the outlet of the reach.

The output data provided by this program permits the comparison of downstream conditions just prior to a breach failure with that after a breach failure and the determination as to whether or not there is a significant increase in the hazard to loss of life as a result of such a failure.

The results of the studies conducted for this report are presented in Section 5.

For detailed information regarding this program refer to the Users Manual for the Flood Hydrograph Package (HEC-1) Dam Safety Version prepared by the Hydrologic Engineering Center, U. S. Army Corps of Engineers, Davis, California.




BY RLS DATE 4/26/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 1 OF \_\_\_\_\_  
PROJECT D8490


MIDDLE CREEK DAM

SPILLWAY RATING



(FROM: SMALL DAMS.)  
FIG. 249 + 251

$$C = 3.75 \times 1.02 = 3.83$$



$$H = 546.5 - 542.5 = 4'$$

$$C = 3.83$$

$$L = 232.5$$

$$Q = CLH^{3/2}$$
$$= 3.83 \times 232.5 \times (4)^{1.5}$$

$$= 7124$$

SAY 7125 CFS




BY RLS DATE 4/30/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 2 OF 2  
PROJECT D8490

MIDDLE CREEK DAM

### SPILLWAY RATING CURVE



BY RLS DATE 4/26/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 3 OF \_\_\_\_\_  
PROJECT 08490

MIDDLE CREEK DAM

### MAXIMUM KNOWN FLOOD AT DAM SITE

PERSONNEL OF THE PENNA. GAME COMMISSION REPORTED THAT THE MAXIMUM KNOWN FLOOD AT MIDDLE CREEK DAM OCCURRED IN JUNE 1972 WHEN THE WATER LEVEL IN THE RESERVOIR REACHED AN ELEVATION 18" ABOVE THE SPILLWAY CREST


$$C = 3.83$$

$$L = 232.5 - (2 \times 1.5) = 229.5$$

$$H = 1.5'$$

$$\begin{aligned} Q &= C L H^{3/2} \\ &= 3.83 \times 229.5 \times (1.5)^{1.5} \\ &= 1615 \text{ CFS} \end{aligned}$$

### DISCHARGE THROUGH LOW POOL SPILLWAY (STOP LOGS REMOVED)




$$C = 2.82 \text{ (KING'S HDBK.)}$$

$$C = 2.82$$

$$\begin{aligned} H &= 542.5 - 540 \\ &= 2.5' \text{ AT NORMAL POOL} \end{aligned}$$

$$L = 2 \times 4 = 8'$$



$$\begin{aligned} Q &= C L H^{3/2} \\ &= 2.82 \times 8 \times (2.5)^{1.5} = 89 \text{ CFS} \end{aligned}$$

BY RLS DATE 4/26/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 4 OF \_\_\_\_\_  
PROJECT D8490

MIDDLE CREEK DAM

DISCHARGE THROUGH OUTLET WORKS

18" x 36" SLUICE GATE INVERT = 531.25

6" x 6" SLUICE GATE INVERT = 531.25

CENTERLINE 18" x 36" GATE = 532.5

CENTERLINE 6" x 6" GATE = 531.5

$$Q = C A \sqrt{2gh}$$

$$C = 0.6$$

AT NORMAL POOL LEVEL 542.5

$$18" H = 542.5 - 532.5 = 10'$$

$$Q = 0.6 \times (1.5 \times 3) \times \sqrt{2 \times 32.2 \times 10} = 69$$

$$6" H = 542.5 - 531.5 = 11'$$

$$Q = 0.6 \times (.5 \times .5) \times \sqrt{2 \times 32.2 \times 11} = 4$$

$$\Sigma Q = 73 \text{ CFS}$$

AT LOW POOL LEVEL 535

$$18" H = 535 - 532.5 = 2.5'$$

$$Q = 0.6 \times (1.5 \times 3) \times \sqrt{2 \times 32.2 \times 2.5} = 34$$

$$6" H = 535 - 531.5 = 3.5$$

$$Q = 0.6 \times (.5 \times .5) \times \sqrt{2 \times 32.2 \times 3.5} = 2$$

$$\Sigma Q = 36 \text{ CFS}$$



BY RLS DATE 4/27/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 5 OF  
PROJECT D8490

MIDDLE CREEK DAM

TOP OF DAM RATING

$$Q = CLH^{3/2}$$

$$C = 2.7 \quad (\text{KING'S HDBK})$$

ELEV. 546.7

$$2.7 \times 112 \times .2^{3/2} = 27$$

$$2.7 \times 25 \times .1^{3/2} = 2$$

$$\Sigma Q = 29$$

ELEV. 546.9

$$2.7 \times 112 \times .4^{3/2} = 77$$

$$2.7 \times 51 \times .2^{3/2} = 12$$

$$\Sigma Q = 89$$

ELEV. 547.3

$$2.7 \times 112 \times .8^{3/2} = 216$$

$$2.7 \times 46 \times .6^{3/2} = 58$$

$$2.7 \times 10 \times .4^{3/2} = 7$$

$$2.7 \times 11 \times .2^{3/2} = 3$$

$$\Sigma Q = 284$$

ELEV. 547.8

$$2.7 \times 112 \times 1.3^{3/2} = 448$$

$$2.7 \times 46 \times 1.1^{3/2} = 193$$

$$2.7 \times 16 \times .65^{3/2} = 23$$

$$2.7 \times 25 \times .45^{3/2} = 20$$

$$\Sigma Q = 634$$

ELEV. 548.2

$$2.7 \times 112 \times 1.7^{3/2} = 670$$

$$2.7 \times 46 \times 1.5^{3/2} = 228$$

$$2.7 \times 16 \times 1.05^{3/2} = 46$$

$$2.7 \times 25 \times .85^{3/2} = 53$$

$$2.7 \times 14 \times .25^{3/2} = 5$$

$$2.7 \times 30 \times .05^{3/2} = 1$$

$$\Sigma Q = 1003$$

ELEV. 549

$$2.7 \times 112 \times 2.5^{3/2} = 1195$$

$$2.7 \times 46 \times 2.3^{3/2} = 433$$

$$2.7 \times 16 \times 1.85^{3/2} = 109$$

$$2.7 \times 25 \times 1.65^{3/2} = 143$$

$$2.7 \times 14 \times 1.05^{3/2} = 41$$

$$2.7 \times 30 \times .85^{3/2} = 63$$


$$\Sigma Q = 1984$$

BY RLS DATE 1/30/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 6 OF  
PROJECT D8490

# DISCHARGE RATING CURVE





BY RLS DATE 4/30/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 7 OF  
PROJECT D8490

MIDDLE CREEK DAM

### SIZE CLASSIFICATION

MAXIMUM STORAGE = 3030 ACRE- FEET

MAXIMUM HEIGHT = 18 FEET

SIZE CLASSIFICATION IS "INTERMEDIATE"

### HAZARD CLASSIFICATION

SEVERAL HOUSES ARE LOCATED ALONG THE  
DOWNSTREAM CHANNEL.

USE "HIGH"

### RECOMMENDED SPILLWAY DESIGN FLOOD

THE ABOVE CLASSIFICATIONS INDICATE USE  
OF AN SDF EQUAL TO THE PROBABLE  
MAXIMUM FLOOD



BY RLS DATE 4/30/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 8 OF 8  
PROJECT D8490

MIDDLE CREEK DAM

## HEC-1 DATA

DRAINAGE AREA = 7.8 SQ. MI.

SUSQUEHANNA BASIN REGION 15 C

$C_p = .82$

$C_T = 2.78$

LONGEST WATER COURSE = 5.49 MI.

LENGTH TO CENTROID = 1.89 MI.

$T_P = C_T (L \times L_{CA})^{.3}$

$T_P = 5.6$

RAINFALL (HMR - 33)

INDEX (200 SQ. MI. - 24 HR.) = 23.4 "

## ZONE 6

### INCREMENTAL RAINFALL

6 HR = 113 %

12 HR = 123 %

24 HR = 132 %

48 HR = 143 %

### PLANIMETERED AREAS (FROM QUAD SHEETS)

ELEV: 542.5 = 365 ACRES

560 = 1123 ACRES

### ZERO STORAGE ELEVATION

ELEV. = 542.5 - (STORAGE  $\times$  3/AREA)  
= 531.8


BY RLS DATE 4/30/79  
CHKD. BY \_\_\_\_\_ DATE \_\_\_\_\_  
SUBJECT \_\_\_\_\_

BERGER ASSOCIATES

SHEET NO. 1 OF \_\_\_\_\_  
PROJECT D 8490

MIDDLE CREEK DAM

SPILLWAY CAPACITY CURVE





FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79

1/4

\*\*\*\*\*

1	A1	MIDDLE CREEK DAM	****	MIDDLE CREEK								
2	A2	CLAY TWP., LANCASTER COUNTY, PA.										
3	A3	ND1 # PA-00731		PA DER # 36-259								
4	B	300	0	15	0	0	0	0	0	0	-4	0
5	B1	5										
6	J	1	9	1								
7	J1	1	.9	.8	.7	.6	.5	.35	.25	.15		
8	K		1									
9	K1											
					INFLOW HYDROGRAPH							
10	M	1	1	7.8								1
11	P		23.4	113	123	132	143					
12	T							1	.05			
13	W	5.6	.82									
14	X	-1.5	-.05	2								
15	K	1	2									
16	K1											
					RESERVOIR ROUTING							
17	Y											
18	Y1	1						1300	-1			
19	Y4	542.5	543	543.5	544	544.5	545	545.5	546	546.5	546.7	
20	Y4	546.9	547.3	547.8	548.2	549						
21	Y5	0	310	879	1615	2488	3520	4626	5839	7125	7694	
22	Y5	8308	9648	11499	13121	16741						
23	YA	0	365	1123								
24	YE	531.8	542.5	560								
25	YF	542.5										
26	YD	546.5										
27	K	99										

1

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT	1
ROUTE HYDROGRAPH TO	2
END OF NETWORK	

\*\*\*\*\*

FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79

\*\*\*\*\*

RUN DATE# 79/04/30.

TIME# 08:09:51.

MIDDLE CREEK DAM \*\*\*\* MIDDLE CREEK  
 CLAY TWP., LANCASTER COUNTY, PA.  
 ND1 # PA-00731 PA DER # 36-259

JOB SPECIFICATION

NO	NHR	NMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	NSTAN
300	0	15	0	0	0	0	0	-4	0
			JOPER	NWT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED



MIDDLE CREEK DAM 8888 MIDDLE CREEK  
CLAY TWP., LANCASTER COUNTY, PA.  
ND1 # PA-00731 PA DER # 36-259

2/19

JOB SPECIFICATION

NO	MHR	MMIN	IDAY	IHR	IMIN	METRC	IPLT	IPRT	INSTAN
300	0	15	0	0	0	0	0	-4	0
			JOPER	NWT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

NPLAN= 1 MRTIO= 9 LRTIO= 1  
RTIOS= 1.00 .90 .80 .70 .60 .50 .35 .25 .15

SUB-AREA RUNOFF COMPUTATION

INFLOW HYDROGRAPH

ISTAQ	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	TAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

INHYD	IUNG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISANE	LOCAL
1	1	7.80	0.00	7.80	0.00	0.000	0	1	0

PRECIP DATA

SPFE	PMS	R6	R12	R24	R48	R72	R96
0.00	23.40	113.00	123.00	132.00	143.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT	STRKR	DLTKR	RTIOL	ERAIN	STRKS	RTIOK	STRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

TP= 5.60 CP= .82 NTA= 0

RECESSION DATA

STRTO= -1.50 ORCSN= -.05 RTIOR= 2.00

UNIT HYDROGRAPH 64 END-OF-PERIOD ORDINATES, LAG= 5.59 HOURS, CP= .81 VOL= 1.00

9.	35.	70.	111.	155.	200.	247.	294.	341.	388.
434.	480.	524.	568.	611.	651.	686.	713.	733.	747.
755.	758.	756.	749.	737.	721.	700.	674.	642.	603.
550.	492.	438.	390.	347.	309.	275.	245.	218.	194.
173.	154.	137.	122.	109.	97.	86.	77.	68.	61.
54.	48.	43.	38.	34.	30.	27.	24.	21.	19.
17.	15.	13.	12.						

END-OF-PERIOD FLOW

NO.DA	HR.MM	PERIOD	RAIN	EXCS	LOSS	COMP Q	NO.DA	HR.MM	PERIOD	RAIN	EXCS	LOSS	COMP Q
-------	-------	--------	------	------	------	--------	-------	-------	--------	------	------	------	--------

SUM 26.77 24.35 2.42 493454.  
( 680. )( 619. )( 61. )( 13973.06 )

## HYDROGRAPH ROUTING

## RESERVOIR ROUTING

ISTAD	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
2	1	0	0	0	0	1	0	0

## ROUTING DATA

QLOSS	CLOSS	AVG	IRES	ISAME	IOPT	IPMP	LSTR
0.0	0.000	0.00	1	0	0	0	0

NSTPS	NSTD	LAG	AMSKK	X	TSK	STORA	ISPRAT
1	0	0	0.000	0.000	0.000	1300.	-1

STAGE	542.50	543.00	543.50	544.00	544.50	545.00	545.50	546.00	546.50	546.70
	546.90	547.30	547.80	548.20	549.00					

FLOW	0.00	310.00	879.00	1615.00	2486.00	3520.00	4626.00	5839.00	7125.00	7694.00
	8308.00	9648.00	11499.00	13121.00	16741.00					

SURFACE AREA=	0.	365.	1123.

CAPACITY=	0.	1302.	13717.

ELEVATION=	532.	543.	560.

CREL	SPWID	COOW	EXPW	ELEV	COOL	CAREA	EXPL
542.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0

## DAM DATA

TOPEL	COOD	EXPD	DAMWID
546.5	0.0	0.0	0.

PEAK OUTFLOW IS 12460. AT TIME 46.25 HOURS

PEAK OUTFLOW IS 11100. AT TIME 46.25 HOURS

PEAK OUTFLOW IS 9748. AT TIME 46.50 HOURS

PEAK OUTFLOW IS 8410. AT TIME 46.50 HOURS

PEAK OUTFLOW IS 7094. AT TIME 46.50 HOURS

PEAK OUTFLOW IS 5855. AT TIME 46.75 HOURS

PEAK OUTFLOW IS 4010. AT TIME 46.75 HOURS

PEAK OUTFLOW IS 2773. AT TIME 47.00 HOURS

PEAK OUTFLOW IS 1559. AT TIME 47.25 HOURS



PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS  
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)  
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS								
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
				1.00	.90	.80	.70	.60	.50	.35	.25	.15
HYDROGRAPH AT	1	7.80	1	14209.	12788.	11367.	9946.	8525.	7104.	4973.	3552.	2131.
	( 20.20)		(	402.34)	( 362.11)	( 321.88)	( 281.64)	( 241.41)	( 201.17)	( 140.82)	( 100.59)	( 60.35)
ROUTED TO	2	7.80	1	12460.	11100.	9748.	8410.	7094.	5855.	4010.	2773.	1559.
	( 20.20)		(	352.83)	( 314.32)	( 276.03)	( 238.14)	( 200.88)	( 165.79)	( 113.54)	( 78.52)	( 44.13)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 .....		INITIAL VALUE	SPILLWAY CREST	TOP OF DAM
ELEVATION		542.48	542.50	546.50
STORAGE		1296.	1302.	3028.
OUTFLOW		0.	0.	7125.

RATIO OF PHF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	548.04	1.54	3843.	12460.	7.00	46.25	0.00
.90	547.69	1.19	3653.	11100.	6.25	46.25	0.00
.80	547.33	.83	3456.	9748.	5.25	46.50	0.00
.70	546.93	.43	3247.	8410.	3.75	46.50	0.00
.60	546.49	0.00	3022.	7094.	0.00	46.50	0.00
.50	546.01	0.00	2785.	5855.	0.00	46.75	0.00
.35	545.22	0.00	2416.	4010.	0.00	46.75	0.00
.25	544.64	0.00	2157.	2773.	0.00	47.00	0.00
.15	543.96	0.00	1870.	1559.	0.00	47.25	0.00

\*\*\*\*\*  
 FLOOD HYDROGRAPH PACKAGE (HEC-1)  
 DAM SAFETY VERSION JULY 1978  
 LAST MODIFICATION 26 FEB 79  
 \*\*\*\*\*



APPENDIX D  
GEOLOGIC REPORT

APPENDIX D

## GEOLOGIC REPORT

### Bedrock - Dam and Reservoir

Formation Name: Gettysburg Formation (also called Hammer Creek Formation).

Lithology: Predominantly red to brown quartz sandstone with interbeds of quartz pebble conglomerate and some red shale. The sandstone beds are typically a few inches to a foot, or more, thick. Grain size ranges from very fine to coarse. Sand grains are angular to sub-rounded quartz, imbedded in a matrix of clay and hematite. The conglomerates consist of pebbles and cobbles of quartzite, vein quartz and sandstone in a matrix of coarse sandstone, clay and hematite. The shale beds are red, thin bedded, non-fissile, composed of clay, hematite and some calcite.

### Structure

The dam is located near the northern side of the Newark-Gettysburg basin, often described as a half-graben, down faulted on the northern side. There is, however, no evidence for a fault in this area. The beds of the Gettysburg Formation strike nearly East-West and dip  $35^{\circ}$  to  $55^{\circ}$  North. No minor faulting has been reported at the dam site.

The dominant direction of air photo fracture traces is about  $N10^{\circ}E$ . The course of Middle Creek is controlled by these fractures at the dam site.

### Overburden

The valley of Middle Creek contains an unusual thickness of unconsolidated materials. The geologic map of the Womelsdorf Quadrangle relates these deposits to the talus that blankets the slopes of nearby South Mountain. Core borings at the site indicate that the deposits consist of sand, gravel and some clay and ore, twenty to forty feet thick. Some swamp deposits, silt, clay and organic muck locally overlies the sand and gravel.

On the valley sides five to ten feet of soil and weathered sandstone blocks overlie the bedrock.



### Aquifer Characteristics

The rocks of the Gettysburg Formation are essentially impermeable, and all ground water movement is along bedding planes and fractures. Where the beds are fractured ground water movement can be quite free. Generally speaking the massive conglomerate and sandstone beds of the dam site seem to resist ground water movement.

### Discussion


The sandstones and conglomerates of the Gettysburg Formation should be excellent dam foundation materials. Only minor amounts of carbonate cement are present, and continued ground water movement is unlikely to weaken the rock. Some leakage under the central section of the dam, along N-S fractures is possible, but it should not affect the soundness of the foundation.

### Sources of Information


1. Geyer, A.R., Buckwalter, T.V., McLaughlin, D.B., and Gray, C. (1963). "Geologic and Mineral Resources of the Womelsdorf Quadrangle". Pa. Geological Survey Atlas A177c.
2. Air Photos, scale 1:24,000, dated 1969.
3. Core boring data in file.



# GEOLOGIC MAP - Middle Creek Dam




(geology from Pa. Geol. Surv. Atlas 177c)




unconsolidated deposits




Gettysburg Fm.- quartz conglomerate



Gettysburg Fm.- sandstone



fault



air photo fracture trace




strike and dip

SCALE 1:24 000

1 MILE

**APPENDIX E**  
**PHOTOGRAPHS**

**APPENDIX E**



Forebay Walls




Left Abutment  
Downstream




Left Abutment  
Wet Area of  
Sidehill

PA-731  
PLATE E-1






Spillway Overflow  
and  
Ice Breakers



Downstream View  
of  
Spillway



Left Side of  
Spillway  
With  
Control Structure

PA-731  
PLATE E-11



Reservoir



Downstream Channel




Two Span Bridge  
Downstream Channel


PA-731  
PLATE E-111

APPENDIX F  
PLATES


APPENDIX F













**AREA-CAPACITY CURVES**



**LOCATION MAP**


SCALE: 1" = 10'








**MAP**  
1" = 10'



### RESERVOIR MAP

1000' 500' 0 1000' 2000'  
SCALE 1" = 1000'









### GENERAL NOTES

- FOR LOGS OF DRILL HOLES AND TEST PITS SEE SHEETS 3 AND 4
- TOPOGRAPHY BASED ON FIELD SURVEY BY PENNSYLVANIA GAME COMMISSION, 1966. ELEVATIONS BASED ON USGS BENCH MARK BM-171, SHOWN ON TOPOGRAPHY.
- UTILITY RELOCATIONS BY OTHERS. FOR RELOCATION OF L.R. 36011, SEE SHEET 2A.
- THE LIMIT OF WORK AREA AS SHOWN IS APPROXIMATE AND MAY BE EXTENDED SUBJECT TO APPROVAL OF THE ENGINEER AND THE GAME COMMISSION.
- FOR LIMIT OF WORK AREA FOR CONSTRUCTION OF L.R. 36011 SEE HIGHWAY DRAWINGS AND/OR SPECIFICATIONS.
- EXTENT OF CLEARING AS SHOWN IS THAT REQUIRED FOR DAM CONSTRUCTION AND WILL BE PAID FOR UNDER ITEM (2) FOR REQUIRED CLEARING FOR CONSTRUCTION OF L.R. 36011 SEE HIGHWAY DRAWINGS AND/OR SPECIFICATIONS.
- FOR OTHER GENERAL NOTES SEE SHEET 5.
- CLEARING AND GRUBBING BORROW AREA WILL BE PAID FOR UNDER ITEM (2)

REVISED	
SYMBOL	CORRECTING
APPROVALS	
APPROVED	PENNSYLVANIA GAME COMMISSION
APPROVED	DIRECTOR, BUREAU OF ENGINEERING AND CONSTRUCTION DEPARTMENT OF PROPERTY AND SUPPLIES
APPROVAL RECOMMENDED	CHIEF ENGINEERING DIVISION - BUREAU OF ENGINEERING AND CONSTRUCTION DEPARTMENT OF PROPERTY AND SUPPLIES
SUBMITTED BY	GANNETT FLEMING CORP. & COMPANY, INC.
COMMONWEALTH OF PENNSYLVANIA RICHARD P. SHAFER, GOVERNOR	
PENNSYLVANIA GAME COMMISSION GLENN L. SOWERS, EXECUTIVE DIRECTOR	
HARRISBURG PENNSYLVANIA	
PROJECT LAYOUT, FOUNDATION EXPLORATION LOCATION AND SITE MAPS, AREA CAPACITY CURVE	
PROJECT NO. 500 2-12 B (46-70)	
CONSTRUCTION OF MIDDLE CREEK DAM MIDDLE CREEK WATERFOWL AREA LANCASTER COUNTY, PENNSYLVANIA FOR THE PENNSYLVANIA GAME COMMISSION	
DATE 10-17-70	GANNETT FLEMING CORP. & COMPANY, INC. ENGINEERS HARRISBURG PENNSYLVANIA

PA. 731  
PLATE III





D.1.4

EL 544.3

10	Reddish-brown silty clay, damp, moist, compact (SC)	10
20	Reddish-brown silty fine SAND with 10% clay and 1 to 5% quartz gravel to 1/2 size. Moist, compact (SM)	20
30	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	30
40	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	40
50	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	50
60	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	60
70	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	70
80	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	80
90	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	90
100	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	100
110	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	110
120	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	120
130	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	130
140	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	140
150	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	150
160	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	160
170	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	170
180	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	180
190	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	190
200	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	200

D.M.8

EL 542.7

10	Reddish-brown silty clay, damp, moist, compact (SC)	10
20	Reddish-brown silty fine SAND with 10% clay and 1 to 5% quartz gravel to 1/2 size. Moist, compact (SM)	20
30	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	30
40	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	40
50	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	50
60	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	60
70	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	70
80	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	80
90	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	90
100	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	100
110	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	110
120	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	120
130	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	130
140	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	140
150	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	150
160	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	160
170	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	170
180	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	180
190	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	190
200	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	200

D.M.14

EL 540.0

10	Reddish-brown silty clay, damp, moist, compact (SC)	10
20	Reddish-brown silty fine SAND with 10% clay and 1 to 5% quartz gravel to 1/2 size. Moist, compact (SM)	20
30	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	30
40	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	40
50	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	50
60	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	60
70	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	70
80	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	80
90	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	90
100	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	100
110	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	110
120	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	120
130	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	130
140	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	140
150	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	150
160	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	160
170	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	170
180	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	180
190	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	190
200	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	200

D.1.17

EL 542.8

10	Reddish-brown silty clay, damp, moist, compact (SC)	10
20	Reddish-brown silty fine SAND with 10% clay and 1 to 5% quartz gravel to 1/2 size. Moist, compact (SM)	20
30	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	30
40	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	40
50	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	50
60	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	60
70	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	70
80	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	80
90	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	90
100	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	100
110	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	110
120	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	120
130	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	130
140	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	140
150	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	150
160	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	160
170	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	170
180	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	180
190	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	190
200	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	200

D.M.18

EL 542.3

10	Reddish-brown silty clay, damp, moist, compact (SC)	10
20	Reddish-brown silty fine SAND with 10% clay and 1 to 5% quartz gravel to 1/2 size. Moist, compact (SM)	20
30	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	30
40	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	40
50	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	50
60	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	60
70	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	70
80	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	80
90	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	90
100	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	100
110	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	110
120	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	120
130	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	130
140	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	140
150	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	150
160	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	160
170	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	170
180	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	180
190	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	190
200	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	200

D.M.19

EL 542.7

10	Reddish-brown silty clay, damp, moist, compact (SC)	10
20	Reddish-brown silty fine SAND with 10% clay and 1 to 5% quartz gravel to 1/2 size. Moist, compact (SM)	20
30	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	30
40	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	40
50	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	50
60	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	60
70	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	70
80	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	80
90	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	90
100	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	100
110	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	110
120	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	120
130	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	130
140	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	140
150	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	150
160	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	160
170	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	170
180	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	180
190	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	190
200	Reddish-brown clayey coarse SAND with 20-30% gravel to 1/2 size. Moist, compact (SC)	200

## GENERAL NOTES

- DRILL HOLES (D.H.) WERE ACCOMPLISHED BY DRIVE BORING PROCEDURE USING A 3" ID x 20' LONG SPOON (UNLESS OTHERWISE NOTED) FOR DISTURBED SAMPLES. THESE SAMPLE SPOONS WERE ADVANCED BY A 300# HAMMER FALLING 18". HOWEVER IN SOME CASES THE OVERBURDEN WAS CORED TO FACILITATE ADVANCING THE BORING. ROCK WAS CORED WITH A 2 1/8" (N.X.) BIT UNLESS OTHERWISE SPECIFIED.
- THE BORINGS INCLUDED ON THESE DRAWINGS ARE THOSE IN OR NEAR THE IMMEDIATE AREA OF THE WORK. THE LOCATION OF THESE BORINGS IS PRESENTED IN THE FOUNDATION EXPLORATION SITE AND LOCATION MAPS.
- LETTER SYMBOLS SUCH AS C, SC, CL, ARE IN ACCORDANCE WITH THE UNIFIED SOIL CLASSIFICATION SYSTEM MIL-STD-891(A) OF THE CORPS OF ENGINEERS, U.S. ARMY.
- THE GROUND WATER LEVEL SHOWN ON THE LOGS REPRESENTS THE LEVEL AT WHICH WATER HAD STABILIZED IN THE HOLE PRIOR TO REMOVAL OF CASING. IT IS NOT NECESSARILY THE LEVEL AT WHICH WATER WAS FIRST ENCOUNTERED IN THE DRILLING OPERATION.
- DESCRIPTION OF SOILS GIVEN ON THE LOGS IS BASED ON EXAMINATION OF QUART SIZE JAR SAMPLES. PRESENCE OF BOULDERS HAS BEEN NOTED ON THE LOGS WHEN THERE WAS A REFUSAL IN THE DRIVING OPERATION WITH SUBSEQUENT CORING. IT SHOULD BE NOTED, HOWEVER, THAT IN MANY INSTANCES COBBLES, OR EVEN SMALL BOULDERS MAY HAVE BEEN PENETRATED BY DRIVING AND MAY NOT THEREFORE BE REFLECTED IN THE LOGS OF THE DRILL HOLES. HIGH RESISTANCE TO DRIVING AS RECORDED IN THE RIGHT HAND COLUMN OF THE LOGS IS CONSIDERED IN MANY TO BE DUE TO A COBBLE OR SMALL BOLDER.
- WATER CONTENTS SHOWN IN RIGHT HAND COLUMN OF DRILL HOLE AND TEST PIT LOGS ARE THE WATER CONTENT (% OF DRY WEIGHT) OF THE TOTAL SAMPLE SOIL RECOVERED. ALL WATER CONTENTS ARE DETERMINED ON MINUS 3/4 MATERIAL UNLESS OTHERWISE NOTED.
- TEST PIT (TP) ARE MACHINE DUG.

ROCK

CONGLOMERATE

CONGLOMERATIC SANDSTONE

SANDSTONE

CLAYSTONE AND SANDY AND SILTY SHALE

NO RECOVERY

REVISED

36-259-3

APPROVED

RECEIVED IN THE OFFICE OF THE WATER & POWER RESOURCES BOARD, DEPARTMENT OF FORESTS & WATERS ON THE 15th DAY OF 1960

APPROVED

APPROVED

APPROVED

APPROVED

APPROVED

COMMONWEALTH OF PENNSYLVANIA

RAYMOND P. SHAPIRO, GOVERNOR

PENNSYLVANIA GAME COMMISSION

GLENN L. BOWERS, EXECUTIVE DIRECTOR

HARRISBURG PENNSYLVANIA

FOUNDATION EXPLORATION

LOGS OF CORE BORINGS

PROJECT NO. 500 2-12 B (46-70)

CONSTRUCTION OF MIDDLE CREEK DAM

MIDDLE CREEK WATERFOWL AREA

LANCASTER COUNTY, PENNSYLVANIA

FOR THE PENNSYLVANIA GAME COMMISSION


SHAPIRO FLEMING CONNOR & CARPENTER, INC.

ENGINEERS


HARRISBURG PENNSYLVANIA

SHEET NO. 3

PA. 731  
PLATE IV










REVISED	
NO.	DATE
APPROVALS	
<p>APPROVED: <i>[Signature]</i> SECRETARY OF THE WATER &amp; POWER COMMISSION</p> <p>APPROVED: <i>[Signature]</i> COMMISSIONER OF FORESTS &amp; WILDLIFE</p> <p>APPROVED: <i>[Signature]</i> SUPERVISOR OF HIGHWAYS</p> <p>APPROVED: <i>[Signature]</i> SUPERVISOR OF HIGHWAYS</p>	
<p>COMMONWEALTH OF PENNSYLVANIA</p> <p>HARRISBURG</p>	
<p>GENERAL PLAN</p> <p>EMBANKMENT SECTIONS AND PLANS</p> <p>PROJECT NO. 500 2-12B(46-70)</p> <p>CONSTRUCTION OF MIDDLE CREEK DAM</p> <p>MIDDLE CREEK WATERFOWL AREA</p> <p>LANCASTER COUNTY, PENNSYLVANIA</p> <p>FOR THE PENNSYLVANIA GAME COMMISSION</p>	
<p>GIBBETT FLEMING CORP. &amp; CARPENTER, INC.</p> <p>ENGINEERS</p> <p>HARRISBURG, PENNSYLVANIA</p>	

PA. 731  
PLATE IV



**PLAN**




**PROFILE ALONG GROUT CURTAIN**


SCALE: 1" = 20'

**LEGEND**


- NX 3" DIA EXPLORATORY HOLE
- EX 1 1/2" DIA PRIMARY HOLE
- EX 1 1/2" DIA SECONDARY HOLE
- EX 1 1/2" DIA TERTIARY HOLE



**PLAN**



**SECTION ALONG GROUT CURTAIN**



**TYPICAL SECTION OF CUTOFF TRENCH**


**GROUTING DETAILING**

NOT TO SCALE


**GENERAL**

1. USE 3/4" HOLES
2. USE 2" HOLES
3. IF AN EX HOLE IS BE ACC PRIOR
4. GROUT CAP AT BACKFILL
5. GROUT CAP AT BACKFILL
6. GROUT CAP AT BACKFILL
7. GROUT CAP AT BACKFILL
8. GROUT CAP AT BACKFILL
9. GROUT CAP AT BACKFILL
10. GROUT CAP AT BACKFILL
11. GROUT CAP AT BACKFILL
12. GROUT CAP AT BACKFILL
13. GROUT CAP AT BACKFILL
14. GROUT CAP AT BACKFILL
15. GROUT CAP AT BACKFILL






**PLAN**  
SCALE 1" = 20'



**ALONG & GROUT CURTAIN**  
SCALE 1" = 20'






**GENERAL NOTES**

1. USE 3/4" DIA BLACK STEEL PIPE FOR 3" (NX) GROUT HOLES.
2. USE 2" DIA BLACK STEEL PIPE FOR 1 1/2" (EX) GROUT HOLES.
3. IF AN EXPANSION PLUG IS USED, THE TOP 18" OF THE HOLE SHALL BE DRILLED TO 3" DIA.
4. GROUT PIPES THROUGH CONCRETE GROUT CAP SHALL BE ACCURATELY PLACED AND FIRMLY SUPPORTED PRIOR TO PLACING CONCRETE.
5. GROUT PIPES SHALL BE CUT FLUSH WITH TOP OF GROUT CAP AFTER GROUTING IS COMPLETED.
6. BACKFILL ALL GROUT HOLES WITH GROUT BEFORE PLACING EMBANKMENT.
7. CONCRETE GROUT CAP SHALL BE PLACED IN 25' MONOLITHS WITH COPPER WATERSTOP BETWEEN EACH MONOLITH.
8. DRILLING NX, 3" DIA. EXPLORATORY HOLES WILL BE PAID FOR UNDER ITEM (7a).
9. DRILLING EX, 1 1/2" DIA. EXPLORATORY HOLES WILL BE PAID FOR UNDER ITEM (7a).
10. ALL GROUT CONNECTIONS WILL BE PAID FOR UNDER ITEM (7a).
11. ALL GROUT PIPE WILL BE PAID FOR UNDER ITEM (7a).
12. ROCK EXCAVATION FOR THE CONCRETE GROUT CAP WILL BE PAID FOR UNDER ITEM (1a).
13. GROUT CAP CONCRETE WILL BE PAID FOR UNDER ITEM (8a).
14. COPPER WATERSTOP WILL BE PAID FOR UNDER ITEM (1a).
15. FOR OTHER GENERAL NOTES SEE SHEET 5.


REVISED	
DATE	CORRECTION
<b>APPROVALS</b> APPROVED: [Signature] PROJECT ENGINEER APPROVED: [Signature] SUPERVISOR APPROVED: [Signature] CHIEF ENGINEER APPROVED: [Signature] CHIEF OF ENGINEERING AND CONSTRUCTION COMMONWEALTH OF PENNSYLVANIA HARRISBURG PENNSYLVANIA	
<b>EMBANKMENT</b> CUTOFF TRENCH AND GROUT CURTAIN PROJECT NO. 800 2-15 (100-701) CONSTRUCTION OF MIDDLE CREEK DAM MIDDLE CREEK NAT'L WOODLAND AREA LANCASTER COUNTY, PENNSYLVANIA FOR THE PENNSYLVANIA GAME COMMISSION	
DESIGNED BY: [Signature] CHECKED BY: [Signature] DRAWN BY: [Signature]	DATE: [Date] SCALE: [Scale]


PA. 731  
PLATE VI



- GENERAL NOTES**
1. ALL SHEET PILING
  2. SHEET PILING
  3. SHEET PILING
  4. SHEET PILING
  5. SHEET PILING
  6. SHEET PILING
  7. SHEET PILING






















**DETAIL "A"**  
**WINGWALL DRAINAGE DETAILS**



- GENERAL CONCRETE AND REINF. STEEL NOTES**
1. ALL EXPOSED EDGES OF CONCRETE SHALL BE CHAMFERED 1" UNLESS OTHERWISE SHOWN OR DIRECTED.
  2. ALL REINFORCING STEEL SPLICE LAPS AND EMBEDMENTS SHALL BE IN ACCORDANCE WITH THE A.C.I. STANDARD BUILDING CODE REQUIREMENTS FOR REINFORCED CONCRETE (A.C.I. 318-63).
  3. ALL BAR BENDING DETAILS SHALL BE IN ACCORDANCE WITH A.C.I. STANDARDS UNLESS OTHERWISE SHOWN.
  4. ALL REINFORCING STEEL SHALL BE PLACED WITHIN 3" OF CONTRACTION JOINTS.
  5. ALL CONTRACTION JOINTS SHALL BE PAINTED WITH 1/8" THICK BITUMINOUS PAINT.
  6. ALL REINFORCING STEEL WILL BE PAID FOR UNDER ITEM 9.

**DETAIL "C"**  
**SHEET PILE DRAINAGE DETAILS**

- GENERAL NOTES**
1. FOR GENERAL NOTES SEE SHEET 5.



REVISED	
SYMBOL	CORRECTIONS
<p><b>APPROVALS</b></p> <p>APPROVED: <i>[Signature]</i>  <small>CHIEF ENGINEERING DIVISION - BUREAU OF ENGINEERING AND CONSTRUCTION  DEPARTMENT OF PROPERTY AND SUPPLIES</small></p> <p>APPROVED: <i>[Signature]</i>  <small>COMMISSIONER OF REVENUE</small></p> <p>APPROVED: <i>[Signature]</i>  <small>CHIEF ENGINEERING DIVISION - BUREAU OF ENGINEERING AND CONSTRUCTION  DEPARTMENT OF PROPERTY AND SUPPLIES</small></p> <p>SUBMITTED BY: <i>[Signature]</i>  <small>GABRIEL FLEMING CORP. &amp; COMPANY, INC.</small></p> <p><b>COMMONWEALTH OF PENNSYLVANIA</b>  <small>EDWARD P. RITCHIE, GOVERNOR</small></p> <p><b>PENNSYLVANIA GAME COMMISSION</b>  <small>GLENN L. BOWEN, EXECUTIVE DIRECTOR</small></p> <p>HARRISBURG PENNSYLVANIA</p> <p><b>SPILLWAY AND OUTLET WORKS</b>  <b>WINGWALL SECTIONS AND MISCELLANEOUS DETAILS</b></p> <p><b>PROJECT NO. 800 2-120 (46-70)</b></p> <p><b>CONSTRUCTION OF MIDDLE CREEK DAM</b>  <b>MIDDLE CREEK WATERFOWL AREA</b>  <small>LANCASTER COUNTY, PENNSYLVANIA</small>  <b>FOR THE PENNSYLVANIA GAME COMMISSION</b></p> <p>DESIGNED BY: <i>[Signature]</i>  <small>GABRIEL FLEMING CORP. &amp; COMPANY, INC.</small></p> <p>ENGINEERS</p>	